

Link Mode	Category	Business	Ports to be opened	Associated domain	Impact of failure to open
DH PaaS	Device on the cloud	Video devices on the cloud	TCP: 39250-39300 UDP: 39291	*.dolynkcloud.com	The video device is offline and other functions cannot be used normally
		IoT devices on the cloud	TCP: 1883, 1884, 39301, 39302	*.dolynksecurity.com	IoT devices cannot be online and other functions cannot be used normally
		Ecological devices on the cloud	OCPP Protocol (TCP: 39288)	*.d-volt.com	The charging pile equipment that uses the OCPP protocol is offline.
		Remotely open the device WEB	TCP: 8900	Dynamic IP	Unable to remotely open the device web (corresponding to the advanced configuration function of the client device)
		Device cloud upgrade	TCP: 443	*.dolynkcloud.com	Unable to perform cloud upgrade via device web
	P2P	P2P	UDP: 0~65535	*.dolynkcloud.com	P2P function cannot be used
LeChange PaaS	Device on the cloud	Device Manage from APP	TCP: 6000~20000	*.imouiot.com, *.imoulife.com, *.easy4ipcloud.com, *.easy4ip.com	The app is unable to discover and manage devices.
	P2P	P2P	UDP: 0~65535		P2P function cannot be used